

Authorised Vehicle Inspection

Last Check PTY LTD


P: 02 8626 3732

ACN: 623340214

ABN: 34623340214

www.lastcheck.com.au

Email: Contact@lastcheck.com.au



LAST CHECK
PRE PURCHASE MOTOR INSPECTIONS



SAMPLE INSPECTION REPORT

Client's Details: Lucy Smith

Date: 30/02/2022

Location: Sydney

State: NSW

Inspector: John Smith

Reporter: Alex Smith

Booking Number: 35842

Inspection Plan: Audi Original Inspection

VEHICLE DETAILS

Inspection Type: Visual Roadside- No Part Disassembly

Make: Audi

Model: Q8

Year: 2020

Registration Number: LDQ...

State Registered: NSW

VIN: WDC1569522J2...

Odometer: 14087

Colour: Black

Number of Doors: 4

Engine Type: Turbo Petrol

Transmission Type: Automatic

Disclaimer: This is a sample report and although very similar, your report might be different. Last Check's report is limited to checking the mechanical and structural condition of the vehicle and we do not intervene in any legal matters between the parties. This report has no legal value and is made to help you know the vehicle's condition or claim warranty repairs if eligible. VIN can be checked visually for tampering; however, it is not guaranteed as we are not law experts. At the same time, the PPSR report (Vehicle History) and registration paper can determine the authenticity of the vehicle. PPSR report is included in almost all pre purchase inspection plans from the lowest to the very highest unless PPSR website is down which rarely happens.

This is a visual inspection only and no component has been removed or fixed. This is our guarantee to the vehicle owner that we never unassemble any parts and if we cause any accidental damages, our insurer will reimburse the owner directly. Last Check will ensure the vehicle is fixed and returned to the owner and there would be absolutely no hassle for the buyer. If you suspect the engine has been replaced in the past, getting the engine number checked at a workshop with hoist facility is recommended. This report gives you valuable insight about the vehicle condition at the time of inspection however it is not a guarantee that it won't go bad shortly after, as mechanical faults can happen without notice on both new and used vehicles.

Each report is rechecked & endorsed by TWO senior technicians other than your inspector before releasing. This is our guarantee and what makes this report different in the industry.

This report is Completely independent and is based on true observation of the vehicle without involving any guesswork. We never report any faults based on speculations and cannot foresee the future. This is our guarantee to both parties that this report is legitimate and is only based on what we have found. Last Check never takes any sides or makes any decision for the client.

We absolutely check all major parts of the vehicle and ensure nothing important has been left behind however we do not or cannot check some minor items on roadside inspection such as alarm/security system, not possible to know if parts are original, minor cosmetics incl. small scratches, dings, kerb rashes, cabin water penetration if not evident, dvd & cd player, car play, cruise, Bluetooth, phone chargers, reverse sensors, steering wheel buttons, automatic wipers, source of leaks unless visible, automated park, routers/brake pad thickness as we don't take the wheels off, lane departure, auto braking, reverse and brake lights, engine number which is on the body of the engine and is normally hidden, anything that is deemed risky when test drive. For more details, please check our terms and conditions.

This inspection is a visual roadside inspection on a third-party vehicle with no permission to open the parts as we have promised the vehicle owner. If you require a more detailed insight about something, after getting disassembly permission from the owner, you can take the vehicle to a workshop with a hoist facility to take parts apart if needed. It is the purchaser's responsibility to view the vehicle before settlement especially if there are concerns about minor cosmetic issues. Although we provide the largest number of pictures, viewing the pictures only can never be like viewing the vehicle in real life. If you are an interstate buyer and don't want to come and see the vehicle before purchase, you are naturally risking it especially since the vehicle has been left with the seller and anything can happen to it even if it has not been used much. For more details, please check our terms and conditions & FAQs.

GENERAL ENGINE INFORMATION

Engine Runs / Sound: **SQUEAKY WHEN IDLING**

Engine Exhaust Smoke: **GOOD**

Computer Fault Diagnosis: **2 ENGINE RELATED FAULT CODES FOUND**

Computer Diagnosis Type: **UNLIMITED & 100% AUDI ORIGINAL DIAGNOSIS**

Engine Timing: **GOOD**

Engine Blow-by: **NO BLOW BY NOTED**

Engine Oil Condition: **POOR**

Engine Oil Level: **LOW**

Engine Bay Oil Leaks: **ENGINE OIL LEAK FOUND**

Extra Comments: **Engine oil leak is from the body of the engine block around the head gasket. It is deemed risky. Refer to the identified issues for more details.**

KEEP IN MIND: If you are buying the vehicle from a dealer in NSW and the vehicle meets the below criteria, you are eligible to receive a statutory warranty. Stat warranty applies to all vehicles younger than 10 years with an odometer of less than 160K and covers most repair costs after purchase for a limited time which is very valuable. These criteria can change at any time, so it is best to do your research before purchase. Hybrid battery charging capacity requires having physical access to the battery which is normally under the rear seats and legally cannot be done on the roadside because of the high voltage surge risks. If the plan you have chosen includes computer scanning, you will know if the battery needs immediate replacement. You can also take the vehicle to an authorised station to be aware of the hybrid battery life & max charging capacity.

ENGINE & TRANSMISSION

Items	Additional Notes	Items	Additional Notes
Engine & Parts: <input checked="" type="checkbox"/> Transmission: <input checked="" type="checkbox"/> Trans Physical Defects: <input checked="" type="checkbox"/> Battery: <input checked="" type="checkbox"/> Battery Cables: <input checked="" type="checkbox"/> Battery Terminal: <input checked="" type="checkbox"/> Battery Wiring: <input checked="" type="checkbox"/> Alternator: <input checked="" type="checkbox"/> Radiator: <input checked="" type="checkbox"/> Radiator Hoses: <input checked="" type="checkbox"/> Thermostat Housing: <input checked="" type="checkbox"/> Cooling / Fan Blade: <input checked="" type="checkbox"/> Water pump: <input checked="" type="checkbox"/> Drive Belts: <input checked="" type="checkbox"/> Carburetor/Injectors: <input checked="" type="checkbox"/>	N/A	Radiator Reservoir: <input checked="" type="checkbox"/> Radiator Cap Health: <input checked="" type="checkbox"/> Coolant Condition: <input checked="" type="checkbox"/> Heater Hoses & Tap: <input checked="" type="checkbox"/> (A/C) Condenser: <input checked="" type="checkbox"/> (A/C) Blower/Fan: <input checked="" type="checkbox"/> (A/C) Assembly: <input checked="" type="checkbox"/> (A/C) Compressor: <input checked="" type="checkbox"/> Intake Manifold: <input checked="" type="checkbox"/> Exhaust Manifold: <input checked="" type="checkbox"/> Cylinder Cap/Seal: <input checked="" type="checkbox"/> Oil Cap Condition: <input checked="" type="checkbox"/> Oil Cap Deposits: <input checked="" type="checkbox"/> Power Steering: <input checked="" type="checkbox"/> Steering Safety: <input checked="" type="checkbox"/>	Engine oil cap did not belong to the vehicle. The seller mentioned he has the original cap and will replace before purchase.

Items	Additional Notes	Items	Additional Notes
Fuel Pump Operation: <input checked="" type="checkbox"/> Fuel Hoses: <input checked="" type="checkbox"/> Engine Fuel Leaks: <input checked="" type="checkbox"/> Air Filter Casing: <input checked="" type="checkbox"/> Starter Motor: <input checked="" type="checkbox"/> Brake Master Cylinder: <input checked="" type="checkbox"/>	N/A	Radiator Operation: <input checked="" type="checkbox"/> Engine Vibration: <input checked="" type="checkbox"/> Alternator Operation: <input checked="" type="checkbox"/> Clutch: <input type="checkbox"/> Super/Turbo Charger: <input checked="" type="checkbox"/> LPG System: <input type="checkbox"/>	N/A

STEERING, BRAKES & SUSPENSION

Items	Additional Notes	Items	Additional Notes
LEFT SIDE & MORE Wheel Assembly: <input checked="" type="checkbox"/> Steering Bushes: <input checked="" type="checkbox"/> Ball Joints: <input checked="" type="checkbox"/> Steering Arms / Tie Rods: <input checked="" type="checkbox"/> Hub Assembly: <input checked="" type="checkbox"/> Strut / Shock: <input checked="" type="checkbox"/>	N/A	RIGHT SIDE & MORE Wheel Assembly: <input checked="" type="checkbox"/> Steering Knuckle: <input checked="" type="checkbox"/> Steering Rack / Box: <input checked="" type="checkbox"/> Steering Arms / Tie Rods: <input checked="" type="checkbox"/> Steering Bushes: <input checked="" type="checkbox"/> Strut / Shock: <input checked="" type="checkbox"/>	N/A

Wheel Bearings: <input checked="" type="checkbox"/>	N/A	Wheel Bearings: <input checked="" type="checkbox"/>	
Leaf / Coil Springs: <input checked="" type="checkbox"/>		Leaf / Coil Springs: <input checked="" type="checkbox"/>	
Sway Bar: <input checked="" type="checkbox"/>		Sway Bar: <input checked="" type="checkbox"/>	
Sway Bar Link: <input checked="" type="checkbox"/>		Sway Bar Link: <input checked="" type="checkbox"/>	
Rims: <input checked="" type="checkbox"/>		Rims: <input checked="" type="checkbox"/>	
Rim Safety: <input checked="" type="checkbox"/>		Rim Safety: <input checked="" type="checkbox"/>	Front right rim did not match the rest. The seller mentioned he will replace before purchase.
Tyres: <input checked="" type="checkbox"/>		Tyres: <input checked="" type="checkbox"/>	
Tyre Connection: <input checked="" type="checkbox"/>		Tyre Connection: <input checked="" type="checkbox"/>	
Tyre Safety: <input checked="" type="checkbox"/>		Tyre Safety: <input checked="" type="checkbox"/>	
Tread Remaining: <input checked="" type="checkbox"/>		Tread Remaining: <input checked="" type="checkbox"/>	
Suspension Bushes: <input checked="" type="checkbox"/>		Suspension Bushes: <input checked="" type="checkbox"/>	
Leaf / Control Arms: <input checked="" type="checkbox"/>		Leaf / Control Arms: <input checked="" type="checkbox"/>	
Brake Calliper: <input checked="" type="checkbox"/>		Strut / Shock: <input checked="" type="checkbox"/>	
Brake Hoses: <input checked="" type="checkbox"/>		Brake Calliper: <input checked="" type="checkbox"/>	
Hub Assembly: <input checked="" type="checkbox"/>		Brake Hoses: <input checked="" type="checkbox"/>	
Steering Knuckle: <input checked="" type="checkbox"/>		Hub Assembly: <input checked="" type="checkbox"/>	
Steering Rack: <input checked="" type="checkbox"/>		LPG Assembly: <input type="checkbox"/>	
Strut / Shock: <input checked="" type="checkbox"/>		LPD Tank: <input type="checkbox"/>	

UNDERBODY

Items	Additional Notes	Items	Additional Notes
Gearbox Damages: <input checked="" type="checkbox"/> Gearbox Guard: <input checked="" type="checkbox"/> Gearbox Assembly: <input checked="" type="checkbox"/> Drive Shafts: <input checked="" type="checkbox"/> Shaft Hubs: <input checked="" type="checkbox"/> Drive Shaft Joints: <input checked="" type="checkbox"/> Drive Shaft Seepage: <input checked="" type="checkbox"/> Transmission Fluid Leaks: <input checked="" type="checkbox"/> Transmission Wires: <input checked="" type="checkbox"/> Transmission Hoses: <input checked="" type="checkbox"/> Transmission Housing: <input checked="" type="checkbox"/> CV Damages: <input checked="" type="checkbox"/> CV Safety: <input checked="" type="checkbox"/> CV Leaks: <input checked="" type="checkbox"/> CV Bushes: <input checked="" type="checkbox"/>	N/A	Engine Housing: <input checked="" type="checkbox"/> Engine Oil Leaks: <input checked="" type="checkbox"/> Fluids & Coolant Leak: <input checked="" type="checkbox"/> Exhaust Pipe Assembly: <input checked="" type="checkbox"/> Exhaust Pipe Leak: <input checked="" type="checkbox"/> Exhaust Pipe Damage: <input checked="" type="checkbox"/> Exhaust Safety: <input checked="" type="checkbox"/> Exhaust Hazardous Rust: <input checked="" type="checkbox"/> Rear Differential: <input checked="" type="checkbox"/> Rear Diff Oil Leaks: <input checked="" type="checkbox"/> Front Differential: <input checked="" type="checkbox"/> Front Diff Oil Leaks: <input checked="" type="checkbox"/> 4WD/AWD System: <input checked="" type="checkbox"/> Transfer Case: <input checked="" type="checkbox"/> Transfer Case Leaks: <input checked="" type="checkbox"/>	N/A

BODY, PAINT & CHASSIS

Items	Additional Notes	Items	Additional Notes
Windscreen: <input checked="" type="checkbox"/> Windscreen Safety: <input checked="" type="checkbox"/> Windscreen Cracks: <input checked="" type="checkbox"/> Glass Trim: <input checked="" type="checkbox"/> Weather Seals / Rubber: <input checked="" type="checkbox"/> Bonnet Stay / Struts: <input checked="" type="checkbox"/> Door Rubber Seals: <input checked="" type="checkbox"/> Door Handles: <input checked="" type="checkbox"/> Door Remote/Key: <input checked="" type="checkbox"/> Door Hinges: <input checked="" type="checkbox"/> Door Alignment: <input checked="" type="checkbox"/> Moulds/Strips: <input checked="" type="checkbox"/> Body Trims: <input checked="" type="checkbox"/> External Mirror: <input checked="" type="checkbox"/> Mirror Operation: <input checked="" type="checkbox"/>	N/A	Bumper / Bull Bar: <input checked="" type="checkbox"/> Boot Tailgate Support: <input checked="" type="checkbox"/> Bumper / Beaver Panel: <input checked="" type="checkbox"/> Headlights: <input checked="" type="checkbox"/> Taillights: <input checked="" type="checkbox"/> Light Lenses: <input checked="" type="checkbox"/> Indicators: <input checked="" type="checkbox"/> Lights Safety: <input checked="" type="checkbox"/> Fuel Cap: <input checked="" type="checkbox"/> Chassis: <input checked="" type="checkbox"/> Wipers: <input checked="" type="checkbox"/> Body Paint: <input checked="" type="checkbox"/> Bodily Rust: <input checked="" type="checkbox"/> Major Collision: <input checked="" type="checkbox"/> Structural Damages: <input checked="" type="checkbox"/>	N/A

INTERIOR & ELECTRONICS

Items	Additional Notes	Items	Additional Notes
<p>Floor Mat: <input checked="" type="checkbox"/></p> <p>Dashboard: <input checked="" type="checkbox"/></p> <p>Glovebox: <input checked="" type="checkbox"/></p> <p>Air Vents: <input checked="" type="checkbox"/></p> <p>Door Trims: <input checked="" type="checkbox"/></p> <p>Interior Lights: <input checked="" type="checkbox"/></p> <p>Interior Mirror: <input checked="" type="checkbox"/></p> <p>Steering Wheel: <input checked="" type="checkbox"/></p> <p>Steering Grip: <input checked="" type="checkbox"/></p> <p>Pedals: <input checked="" type="checkbox"/></p> <p>Interior Assembly: <input checked="" type="checkbox"/></p> <p>Combination Switch: <input checked="" type="checkbox"/></p> <p>Stock Switches: <input checked="" type="checkbox"/></p> <p>Light Switches: <input checked="" type="checkbox"/></p> <p>Internal Storage: <input checked="" type="checkbox"/></p>	N/A	<p>Seats: <input checked="" type="checkbox"/></p> <p>Seat Belts: <input checked="" type="checkbox"/></p> <p>Belts Buckles: <input checked="" type="checkbox"/></p> <p>Seat Adjusters: <input checked="" type="checkbox"/></p> <p>Front & Rear Wiper: <input checked="" type="checkbox"/></p> <p>Wiper Functionality: <input checked="" type="checkbox"/></p> <p>Washers: <input checked="" type="checkbox"/></p> <p>Door Locks: <input checked="" type="checkbox"/></p> <p>Windows: <input checked="" type="checkbox"/></p> <p>Locks Operation: <input checked="" type="checkbox"/></p> <p>Windows Operation: <input checked="" type="checkbox"/></p> <p>Cluster Gauges: <input checked="" type="checkbox"/></p> <p>Hazard Switch: <input checked="" type="checkbox"/></p> <p>Attention Lights: <input checked="" type="checkbox"/></p> <p>Console: <input checked="" type="checkbox"/></p>	N/A


Items	Additional Notes	Items	Additional Notes
<p>Cluster: <input checked="" type="checkbox"/></p> <p>Cluster Lenz: <input checked="" type="checkbox"/></p> <p>Brake Light: <input checked="" type="checkbox"/></p> <p>Warning Lights: <input checked="" type="checkbox"/></p> <p>Engine Light: <input checked="" type="checkbox"/></p> <p>Odometer: <input checked="" type="checkbox"/></p> <p>SRS <input checked="" type="checkbox"/></p> <p>SRS Safety Warning <input checked="" type="checkbox"/></p> <p>Gear Shifter/Selector: <input checked="" type="checkbox"/></p> <p>Shifter Damages: <input checked="" type="checkbox"/></p> <p>Parking Brake: <input checked="" type="checkbox"/></p> <p>Brake Engagement: <input checked="" type="checkbox"/></p> <p>Roof Lining: <input checked="" type="checkbox"/></p> <p>Sun Visors: <input checked="" type="checkbox"/></p> <p>Sun Visor Mounts: <input checked="" type="checkbox"/></p> <p>Visor Safety: <input checked="" type="checkbox"/></p> <p>Air Flow Control: <input checked="" type="checkbox"/></p>	N/A	<p>AC Switches: <input checked="" type="checkbox"/></p> <p>AC Buttons: <input checked="" type="checkbox"/></p> <p>Recycle Control: <input checked="" type="checkbox"/></p> <p>AC Operation: <input checked="" type="checkbox"/></p> <p>Heater Operation: <input checked="" type="checkbox"/></p> <p>Blower Operation: <input checked="" type="checkbox"/></p> <p>Blower Noise: <input checked="" type="checkbox"/></p> <p>Fan Direction Switch: <input checked="" type="checkbox"/></p> <p>Air Flow: <input checked="" type="checkbox"/></p> <p>Radio: <input checked="" type="checkbox"/></p> <p>Radio Operation: <input checked="" type="checkbox"/></p> <p>Speakers: <input checked="" type="checkbox"/></p> <p>Horn: <input checked="" type="checkbox"/></p> <p>Horn Operation: <input checked="" type="checkbox"/></p> <p>Costly Imperfections: <input checked="" type="checkbox"/></p> <p>Sunroof/Convertible Roof: <input checked="" type="checkbox"/></p> <p>Sun/Convertible Operation: <input checked="" type="checkbox"/></p>	N/A

IN REAL LIFE

NOTE: LOTS OF PICTURES HAVE BEEN TAKEN FROM THE VEHICLE TO GIVE YOU A CLEAR IMAGE OF ALL DETAILS. PLEASE REFER TO THE SEPARATE PICTURE ALBUM IN YOUR REPORT LINK.



REAR PART



RIGHT SIDE



LEFT SIDE



PANELS & MAJOR COSMETICS




PAINT & RUST ASSESSMENT



COLLISION ASSESSMENT




UNDERBODY & OIL LEAKS



SUSPENSION




CHASSIS & EXHAUST SYSTEM



TYRES & ABS BRAKE SYSTEM



ENGINE & TRANSMISSION



FLUIDS CONDITION



100% ORIGINAL COMPUTER DIAGNOSIS



INSTRUMENT CLUSTER & ODOMETER



INFOTAINMENT SYSTEM




ELECTRONICS



SUNROOF & CONVERTIBLE ROOF



INTERIOR & UPHOLSTERY



INTERIOR LIGHTS & OPTIONS



SEATS & SEAT BELTS




AIRCONDITIONING & HEATER




SERVICE LOGBOOK



REVERSE CAMERA



VIN & COMPLIANCE



COMPLETE TEST DRIVE



REMOTE & CENTRAL LOCKING



DOOR HANDLES



PLUS, ADDITIONAL EXTRA LARGE PICTURE ALBUM

**YOU HAVE HUNDREDS OF MORE
PICTURES!!**

**CHECK OUT YOUR ADDITIONAL PICTURE ALBUM TO SEE
HUNDREDS OF MORE PICTURES VALUABLE FOR YOUR
DECISION-MAKING.**

WITH LOVE - LAST CHECK

PLUS, ATTACHED PPSR VEHICLE HISTORY REPORT

CHECK OUT YOUR ATTACHED
PPSR VEHICLE HISTORY REPORT!

REGISTRATION STATUS
WRITTEN OFF DATA
FINANCE OWING
STOLEN VEHICLE DATA
VEHICLE RECALLS

ROAD TEST

Items	Additional Notes	Items	Additional Notes
Inhibitor Switch: <input checked="" type="checkbox"/> Steering Vibrations: <input checked="" type="checkbox"/> Wheel Alignment: <input checked="" type="checkbox"/> Brake Operation: <input checked="" type="checkbox"/> Gearbox Operation: <input checked="" type="checkbox"/> Gas Operation: <input checked="" type="checkbox"/> Speedometer: <input checked="" type="checkbox"/> Tachometer: <input checked="" type="checkbox"/> Odometer: <input checked="" type="checkbox"/> C.V Joints: <input checked="" type="checkbox"/> Steering: <input checked="" type="checkbox"/>	<p>The gas pedal was missing the rubber but the seller mentioned he has the part and will rectify the issue before purchase.</p>	Driveshaft vibrations: <input checked="" type="checkbox"/> Ride Quality: <input checked="" type="checkbox"/> Engine Performance: <input checked="" type="checkbox"/> Engine Smoke: <input checked="" type="checkbox"/> Suspension Performance: <input checked="" type="checkbox"/> Transmission Performance: <input checked="" type="checkbox"/> Transmission Whine: <input checked="" type="checkbox"/> Differential Whine: <input type="checkbox"/> Clutch Pedal: <input type="checkbox"/> Clutch Operation: <input type="checkbox"/> Turbo/Super Charger: <input checked="" type="checkbox"/>	N/A

Speed Limit: Legal

ATTENTIONS

*** **WARNING** ***

WRITTEN OFF VEHICLE!

According to the PPSR record (Vehicle History Report), this vehicle is a Repairable Write-Off. The overall value of this vehicle will be below the market value. Even if the vehicle is in a good shape, the resale value will be below the average and in some cases, it is hard to resell the vehicle.

A full copy of the vehicle history report is a part of your report, please find the attached copy for your reference.

Other Notes: The seller mentioned that he is selling the vehicle on behalf of a friend. This transaction can be potentially very risky if the vehicle owner is not involved. We highly recommend dealing with the owner of the vehicle and personally witnessing their signature on the registration paper should you want to go ahead with the purchase.

IDENTIFIED ISSUES

Please Note: To make the report easy to understand for all, only the faults of the vehicle are listed here. Other than what is listed here, the vehicle did not need any other repairs. Please note that not all worn but still usable parts are considered faulty in a used vehicle, and we do not list them here to avoid confusion and creating unnecessary costs for the buyer. Cosmetics and the rest of the vehicle has been in line with the age. If you decide to go ahead, ensure you see the vehicle in person and you are happy with the small cosmetics, wear and tear and the vehicle smell. We do not recommend remote buying because of the legal risks and the cosmetic likings specially if the vehicle is valuable.

ISSUES FOUND:

- The vehicle has some superficial scratches which are in line with the age but no big dent or bodily damage could be seen.
- The roof and bonnet are hail damaged. It affects the resale value of the car and most insurers won't insure the car in this shape!
- Two engine related fault codes were found in the module that needs immediate attention and further diagnosis.

Fault code 1: P0301 _ Cylinder 1 Misfire Detected

Fault code 2: P0327_ Knock Sensor 1 Circuit Low Input (Bank 2 or Single Sensor)

- The radiator has a crack on the bottom right side which cannot be repaired. We recommend immediate replacement
- Fresh oil leak was found under the transmission although the transmission performance was still good _ it can be costly to fix in this model vehicle.
- Fresh oil leak was found from the sides of the engine block around the head gasket although the head gasket has not yet been affected. Urgent attention is needed and will be costly for this model vehicle.
- The rear left shock is leaking fluid and needs replacement.
- The vehicle has been involved in multiple accidents including a high impact one on the front right side. The chassis has also been affected and fixed as a result. This vehicle can never be like before. Consider this before making the final decision.

- The engine had excessive Blowby _ it will be costly to repair as the engine block will need opening and closing to fix the issue.
- The right side of the car, roof, bonnet and tailgate have been resprayed in the past and the paint job does not look professional. It only has cosmetic value but it can negatively affect the resale value of the car.
- The engine had excessive Blowby _ it will be costly to repair as the engine block will need opening and closing to fix the issue.
- The left side electric mirror is not functional. The motor needs replacement.
- The rear left belt buckle needs to be replaced_ The vehicle will not pass registration in the current condition.
- Turbocharger functionality was poor and noisy. The turbocharger is still functional but consider replacement in near future. We highly recommend getting a valid repair quote as the repair cost can be more than expected in this model vehicle
- A/C Compressor needs replacement- we recommend using only the original part for this model vehicle which can be costly.
- Central locking is not working on the rear right door. It is a safety risk and urgent repair is needed.
- The battery is about to fail but it is still functional. The registration is about to expire in a couple of months, we recommend replacing the battery at the time of rego renewal
- The engine oil and brake fluid need replacement and the normal service is due. We highly recommend using full synthetic engine oil for this model vehicle


ADVISORY COMMENTS ONLY _ (IF APPLICABLE)

Please note, advisory comments are not considered as faults of the vehicle. Their sole purpose is just to assist with your decision making.

- The reliability score of this car is low which means the condition is subject to change without notice. The repair cost of the vehicle including parts and labour is also relatively high.
- According to PPSR Car History Report, this vehicle is written off. The resale value of the vehicle is below the average and some insurers might not insure the vehicle in this shape. Please consider these facts before paying any deposits

**RECOMMENDATION
CONTENT MIGHT VARY AND
WILL BE PROVIDED IN THE
REAL REPORT**





IS MY VEHICLE RELIABLE?

CONTENT MIGHT VARY AND
WILL BE PROVIDED IN THE
REAL REPORT



**BEWARE OF
SCAMS**



BE CAREFUL, NOT SORRY!

**CONTENT MIGHT VARY AND
WILL BE PROVIDED IN THE
REAL REPORT**

