Authorised Vehicle Inspection

www.lastcheck.com.au

Last Check PTY LTD

ACN: 623340214

ABN: 34623340214

Phone: 02 7805 3730

Email: Contact@lastcheck.com.au

LAST CHECK

PRE PURCHASE MOTOR INSPECTIONS

ELECTRIC VEHICLE INSPECTION

Client's Details: Lucy Smith	**Physical Inspectors: John**
Date: 4/11/2025	**Technical Inspector: Alex**
Location: Seller's Address	**Reporter: Sean**
State: NSW	**Inspection Plan: Electric Car Inspection**

VEHICLE DETAILS

Inspection Type: Visual Roadside- No Part Disassembly	**VIN: WDC1569522J2...**
Make: Tesla	**Odometer: 38681**
Model: Y	**Colour: Black**
Year: 2023	**Number of Doors: 4**
Registration Number: LDQ...	**Motor Type: Electric**
State Registered: NSW	**Battery Type: AU Permitted**

Three Technicians Have Been Involved in Making this Report!

1. **Physical Inspection** by One Senior Inspector at the Seller's Address
2. **PPSR Vehicle History** by Another, After the Inspection by Checking the VIN Online
3. **Report** by a Technical Reporter & Reviewer Checking the Work, Pictures, PPSR Report & More

ELECTRIC MOTOR & BATTERY

Items	About Electric Motor	Items	About EV Battery
Motor Assembly: ☒	Please note that the electric motor in most electric vehicles is concealed and cannot be seen without disassembly. In some vehicles, it may be partially visible, but access is still limited without using a hoist and removing the splash cover from underneath. The electric motor is the core component of any EV. Most of the checks outlined here cannot be performed visually, and we rely on performance indicators to assess its condition. This is generally sufficient before purchasing the vehicle or prior to the end of the warranty period, provided everything is functioning as expected. However, if you wish to physically inspect all components, you can take the vehicle to a licensed EV garage, with permission for parts disassembly. Please be aware that this can be a significant and costly task and should only be carried out at a workshop with an EV repair licence.	Battery Performance: ☒	Please note that the electric battery in electric vehicles is fully concealed and should not be touched without the proper equipment. The battery's location varies between different vehicles but is usually situated in the floor beneath the floor mats and seats. The battery cannot be visually inspected, and it is generally unnecessary to do so before purchasing or at the end of the warranty period. EVs, however, are essentially computers on wheels and come equipped with advanced software that indicates performance, faults, state of charge, and other metrics. On average, an EV battery loses about 2-3% of its charge capacity per year. However, the rate of degradation can vary based on several factors and may differ among models. While we can assess the health and performance of the battery, we cannot see the exact numeric charge capacity. An EV with only 80% charge capacity can still perform adequately for its age. We conduct various tests on the battery and check the dashboard monitors to evaluate its performance, which is generally sufficient before purchase or at the end of the warranty period however if you require the exact numeric charge capacity, you should contact the manufacturer for advice.
Motor Physical Damage: ☒		Battery Discharge: ☒	
Motor Sound: ☒		Battery State of Charge: ☒	
Motor Idling: ☒		Battery Holding Charge: ☒	
Visible Electrical Cables: ☒		Battery Cooling System: ☒	
Motor Housing: ☒		Battery Overheating: ☒	
Power Control Unit: ☒		BMC Functionality: ☒	
DC Convertor: ☒		Battery Range: ☒	
Power Electronics: ☒		Range Estimation: ☒	
Motor Power: ☒		Battery Physical Damage: ☒	
Traction Battery Pack: ☒		AC Battery Drainage: ☒	
Motor Cooling System: ☒		Heater Battery Drainage: ☒	
Fluids: ☒		Steering Battery Drainage: ☒	
Motor Controller: ☒		Battery Monitor: ☒	
PMSM Performance: ☒		Battery Failing: ☒	
Unexpected Smoke: ☒		Battery Error/Warnings: ☒	

STEERING, BRAKES & SUSPENSION

Items	Police/Legal Investigation	Items	Police/Legal Investigation
LEFT SIDE & MORE	This section is dedicated to forensic investigations and findings requested by law enforcement, the court, or a tribunal.	**RIGHT SIDE & MORE**	This section is dedicated to forensic investigations and findings requested by law enforcement, the court, or a tribunal.
Wheel Assembly: ☒		Wheel Assembly: ☒	
Steering Bushes: ☒		Steering Bushes: ☒	
Ball Joints:☒		Ball Joints:☒	
Steering Arms / Tie Rods:☒		Steering Arms / Tie Rods:☒	
Hub Assembly:☒		Hub Assembly:☒	
Strut / Shock:☒		Strut / Shock:☒	
Visible Suspension Parts:☒		Visible Suspension Parts:☒	
Sway Bar:☒		Sway Bar:☒	
Rims:☒		Rims:☒	
Tyres:☒		Tyres:☒	
Tyre Tread:☒		Tyre Tread:☒	
Brake System:☒		Brake System:☒	
Brake Calliper: ☒		Brake Calliper: ☒	
Brake Functionality: ☒		Brake Functionality: ☒	
LS Variant Specific Parts: ☒		RS Variant Specific Parts: ☒	

BODY, PAINT & CHASSIS

Items	Police/Legal Investigation	Items	Police/Legal Investigation
Windscreen: ☒	This section is dedicated to forensic investigations and findings requested by law enforcement, the court, or a tribunal. Last Check performs legal & forensic inspections for Insurance, Tribunal, NCAT, Court & Police.	Bumper / Bull Bar: ☒	This section is dedicated to forensic investigations and findings requested by law enforcement, the court, or a tribunal. Last Check performs legal & forensic inspections for Insurance, Tribunal, NCAT, Court & Police.
Windscreen Safety: ☒		Boot Tailgate Support: ☒	
Windscreen Cracks: ☒		Bumper Safety: ☒	
Glass Trim: ☒		Headlights: ☒	
Weather Seals / Rubber: ☒		Taillights: ☒	
Bonnet Stay / Struts: ☒		Light Lenses: ☒	
Door Rubber Seals: ☒		Indicators: ☒	
Door Handles: ☒		Lights Performance: ☒	
Door Remote/Key: ☒		Charging Port: ☒	
Door Hinges: ☒		Chassis: ☒	
Door Alignment: ☒		Wipers: ☒	
Internal Strips: ☒		Body Paint: ☒	
Body Trims: ☒		Bodily Rust: ☒	
Mirror Operation: ☒		Major Collision Signs: ☒	
External Mirror: ☒		Structural Damages ☒	
Variant Specific Parts: ☒		Non-Repairable Parts: ☒	

INTERIOR & ELECTRONICS

Items	Police/Legal Investigation	Items	Police/Legal Investigation
Floor: ☒	This section is dedicated to forensic investigations and findings requested by law enforcement, the court, or a tribunal.	Seats: ☒	This section is dedicated to forensic investigations and findings requested by law enforcement, the court, or a tribunal.
Floor Mat: ☒		Seat Belts: ☒	
Dashboard: ☒	Last Check performs legal & forensic inspections for Insurance, Tribunal, NCAT, Court & Police.	Belts Operation: ☒	Last Check performs legal & forensic inspections for Insurance, Tribunal, NCAT, Court & Police.
Glovebox: ☒		Seat Adjusters: ☒	
Air Vents: ☒		Front & Rear Wipers: ☒	
Door Trims: ☒		Wiper Functionality: ☒	
Interior Lights: ☒		Windscreen Washers: ☒	
Interior Mirror: ☒		Door Locks: ☒	
Steering Wheel: ☒		Windows: ☒	
Steering Grip: ☒		Locks Operation: ☒	
Brake Pedal: ☒		Windows Operation: ☒	
Accelerator Pedal: ☒		Cluster Gauges: ☒	
Combination Switch: ☒		Hazard Switch: ☒	
Stock Switches: ☒		Attention Lights: ☒	
Light Switches: ☒		Interior Assembly: ☒	
Internal Storage: ☒		Console: ☒	

Items	Police/Legal Investigation	Items	Police/Legal Investigation
Cluster/Head Unit Assembly:☒	This section is dedicated to forensic investigations and findings requested by law enforcement, the court, or a tribunal. Last Check performs legal & forensic inspections for Insurance, Tribunal, NCAT, Court & Police.	AC Switches: ☒	This section is dedicated to forensic investigations and findings requested by law enforcement, the court, or a tribunal. Last Check performs legal & forensic inspections for Insurance, Tribunal, NCAT, Court & Police.
Cluster/Head Unit Lenz:☒		AC Buttons: ☒	
General Warning Lights:☒		Recycle Control:☒	
Brake Emergency Light:☒		AC Operation: ☒	
EV Motor Malfunction Light:☒		Heater Operation: ☒	
Battery Emergency Light:☒		Blower Operation: ☒	
Odometer:☒		Blower Noise: ☒	
Parking Brake:☒		Fan Direction Switch: ☒	
Brake Engagement:☒		Air Flow: ☒	
Sun Visors:☒		Radio: ☒	
Sun Visor Mounts: ☒		Radio Operation: ☒	
Sun Visor Safety:☒		Speakers: ☒	
Air Flow Control: ☒		Horn: ☒	
Infotainment System:☒		Horn Operation: ☒	
Infotainment LCD:☒		Sunroof/Roof Liner ☒	
Infotainment Touch Sensitivity:☒		Sunroof/Roof Liner Damage:☒	
Infotainment System Warnings:☒		Sunroof/Liner Leak Mark:☒	
Infotainment Malfunction:☒		Variant Specific Parts:☒	

INSPECTION PICTURES

NOTE: LOTS OF PICTURES HAVE BEEN TAKEN FROM THE VEHICLE TO GIVE YOU A CLEAR IMAGE OF ALL DETAILS. PLEASE REFER TO THE SEPARATE PICTURE ALBUM IN YOUR REPORT LINK.

REAR PART

RIGHT SIDE

LEFT SIDE

PANELS & MAJOR COSMETICS

PAINT & RUST ASSESSMENT

COLLISION ASSESSMENT

UNDERBODY



SUSPENSION

CHASSIS

TYRES & SAFETY

UNDER THE HOOD

FLUIDS CONDITION & LEAKS

INSTRUMENT CLUSTER & ODOMETER



EV BATTERY & RANGE



ELECTRONICS



SUNROOF & CONVERTIBLE ROOF

INTERIOR & UPHOLSTERY

INTERIOR LIGHTS & OPTIONS

SEATS, BELTS & SAFETY

AIRCONDITIONING & HEATER



SERVICE HISTORY

REVERSE CAMERA

VIN & COMPLIANCE

COMPLETE TEST DRIVE

LIGHTS & SAFETY

OPTIONAL AVILOO EV BATTERY TEST

ACCURATE BATTERY STATE OF HEALTH, REAL DRIVING RANGE & DEAD CELL DETECTION

FULL PPSR VEHICLE HISTORY

REPORT WILL BE PROVIDED SEPARATELY- WRITTEN OFF, STOLEN, FINANCE, RECALS & REGO

Australian Government
Australian Financial Security Authority

PPSR Personal Property Securities Register

19/08/2019

Serial Number Search Certificate

This is a serial number search certificate for a serial number search

This Search certificate is provided under section 174 of the *Personal Property Securities Act 2009*

Search certificate number: 7047301338830001
Search number: 704730133883

This search certificate reflects the data contained in the PPSR at 19/08/2019 18:44:13 (Canberra Time).

Search Criteria Details

Serial number search type: VIN
Motor vehicle: [redacted]6P022668
PPSR registration state searched: Current

PPSR Registration Details

There is no security interest or other registration kind registered on the PPSR against the serial number in the search criteria details.

Vehicle Recall Information

OPTIONAL ODOMETER ROLLBACK & VIN CHECK

IDENTIFIES REAL VIN & ODOMETER — ALL EVs MINUS TESLA WHICH IS TAMPERPROOF



AUSTRALIAS LARGEST PICTURE ALBUM INCLUDED

200 TO 500 PICTURES IN A SEPARATE ALBUM

OPTIONAL FULL WALKAROUND VIDEO

SENT SEPARATELY WITH FULL REPORT

RECEIPT OF PAYMENT incl. GST

SENT SEPARATELY WITH FULL REPORT

PAYMENT RECEIPT

Last Check PTY LTD
www.lastcheck.com.au
ACN: 623340214
Phone: 02 7805 3730
Email: Contact@lastcheck.com.au

LAST CHECK
PRE PURCHASE MOTOR INSPECTIONS

INVOICE #39650
DATE: OCTOBER 15, 2025

CLIENT: FIRST & LAST NAME OR COMPANY NAME

ROADSIDE VEHICLE INSPECTION

DESCRIPTION	TYPE	UNIT	AMOUNT
Inspection of Vehicle …	Pre Purchase	1	$000
GST			$000

COMPLETE TEST DRIVE

Items	Police/Legal Investigation	Items	Police/Legal Investigation
Steering Operation: ☒	**This section is dedicated to forensic investigations and findings requested by law enforcement, the court, or a tribunal.**	**Ride Quality:** ☒	**This section is dedicated to forensic investigations and findings requested by law enforcement, the court, or a tribunal.**
Steering Vibrations: ☒		**Motor Performance:** ☒	
Wheel Alignment: ☒	Last Check performs legal & forensic inspections for Insurance, Tribunal, NCAT, Court & Police.	**Motor Unwanted Smoke:** ☒	Last Check performs legal & forensic inspections for Insurance, Tribunal, NCAT, Court & Police.
Brake Operation: ☒		**Motor Acceleration:** ☒	
Brake Pedal Feeling: ☒		**Motor Overheating:** ☒	
Accelerator Operation: ☒		**Motor Warning Lights:** ☒	
Speedometer: ☒		**EV Battery Performance:** ☒	
Odometer: ☒		**EV Battery Drainage:** ☒	
C.V Functionality: ☒		**EV Battery Overheating:** ☒	
Regen Braking Performance: ☒		**Battery Warnings:** ☒	
Regen Braking Noise: ☒		**Suspension Performance:** ☒	

Road Test Speed: Local Max Legal

WE HAVE MADE IT EASY FOR YOU!

This Report Is Well-Organised & Easy to Understand, Requiring No Technical Knowledge. You Won't Need to Search Through Multiple Pages to Find the Issues.

All Identified Issues Are Consolidated Below in One Place for Your Convenience. Additionally, We've Provided Recommendations Below the Issues to Help You Better Understand the Process of Buying a Used Vehicle, Including Potential Risks & Important Considerations.

WARNINGS

THIS CAR IS WRITTEN OFF

According to the PPSR record, this vehicle is a Repairable Write-Off. Its market and resale value will be lower than average, and it may be difficult to sell.

A full copy of the Vehicle History Report is attached for reference.

FINANCE IS OWING ON THE VEHICLE!!

Please note that there is finance owing on this vehicle. Any existing finance remains attached to the motorcycle and will transfer to the new owner upon purchase. We strongly recommend ensuring the seller clears the finance before full payment is made. Details of the financial encumbrance can be found in the collateral section of the attached PPSR report.

IDENTIFIED ISSUES

ALL ISSUES NEATLY LISTED IN ONE PLACE:

From A to Z, All Issues of the Vehicle Will Be Listed Here, Revealing the Severity, What Is Best to Do, Whether the Repairs Can Be Costly or Not, as Well as Recommendations on What to Do.

No Technical Knowledge Is Needed to Understand the Report. All Issues Will Be Listed in Simple Yet Accurate and Professional Language That Can Be Used to Get a Repair Quote.

At the End, the Report Will Contain a Personal Recommendation Tailored to the Condition of the Vehicle and What Is Best to Do. If the Vehicle Is Perfect, It Will Be Endorsed, and the Report Can Be Used in Future When Selling the Vehicle as an Endorsed Condition of the Vehicle at the Time of Inspection, Along With Hundreds of Pictures Which Will Add Value to the Vehicle and Make the Resale Process Easier.

Full Mechanical & Structural Inspection Including:

- **EV Battery Performance Issues**
- **EV Motor Performance Issues**
- **Dual Motor Problems**
- **Fluid Leaks**
- **Bodily Damages Needing Repair**

- **Chassis Issues**
- **Suspension Problems**
- **Past Collisions**
- **Body Rust**
- **Fluids Condition**
- **Electronics Issues**
- **Interior & Exterior Issues**
- **Test Drive Concerns**
- **Safety Concerns**
- **Tyres**
- **Brake System**
- **Lights**
- **And Everything Else Based on the Vehicle Type**

This Report Will Be Issued After an Initial Phone Call With Your Inspector, Who Will Explain Everything to You, Answer Your Technical Questions, and Guide You Toward Making the Best Decision.

UNSURE OF WHAT TO DO?

WE DO NOT LIMIT YOUR CALLS AFTER THE INSPECTION!

WE'RE HAPPY TO KEEP HELPING YOU AND BE YOUR PROFESSIONAL ADVISER UNTIL YOU FINALISE YOUR PURCHASE OR HELP YOU CHOOSE ANOTHER VEHICLE.

RECOMMENDATION

INFORMATION ABOUT YOUR RIGHTS, DEALING WITH PRIVATE SELLERS AND DEALERS IN AUSTRALIA, DEALER'S COMPULSORY WARRANTY & MANUFACTURER WARRANTY, IN THE FINAL REPORT

IS MY VEHICLLE RELIABLE

LEARN HOW RELIABLE YOUR VEHICLE IS AND WHAT OTHER VEHICLES YOU COULD GET FOR THE SAME INVESTMENT, IN THE FINAL REPORT

BEWARE OF
SCAMS

BE CAREFUL, NOT SORRY!

LEARN HOW TO AVOID SCAMMERS AND THE RIGHT WAY TO PAY FOR YOUR VEHICLE IN AUSTRALIA, IN THE FINAL REPORT